

Metal (Oxide) Film Resistors

Discontinued

ERG(X)S type (Small size)

(0.5 W, 1 W, 2 W, 3 W, 5 W)

ERG(X)F type (Anti-heat conducting for PCB)


(1 W, 2 W, 3 W, 5 W)




Features

- Miniaturized 50 % smaller compared to existing models
- Non-flammable
- High reliability
- Automatic insertion
- Reference standards : IEC 60115-2, IEC 60115-4, JIS C 5201-4, EIAJ RC-2138
- RoHS compliant

Explanation of part numbers




The above example 1 shows a small metal film resistor, 2 W power rating, resistance value of 1.0 Ω , tolerance ± 5 %, and package of radial taping.




The above example 2 shows a small metal oxide film resistor, 2 W power rating, resistance value of 10 k Ω , tolerance ± 5 %, and package of radial taping.

Construction



Dimensions in mm (not to scale)



Unit : mm Mass Dimensions Part No. (Weight) L øD (g/ pc) 0.65 ^{±0.05} 6.35 +0.65 - 0.35 2.3 +0.5 - 0.3 30.0 ^{±3.0} 0.26 ERG(X)12S 0.65 ±0.05 ERG(X)1S 2.8 ^{±0.5} 30.0 ±3.0 9.00 +1.50 - 1.00 0.33 0.80 ERG(X)1F ERG(X)2S 4.0 ^{±1.0} 30.0 ^{±3.0} 0.80 ^{±0.05} 12.00 ^{+1.50} _{- 1.00} 0.66 ERG(X)2F ERG(X)3S l5.00 ^{±1.50} 5.5 ^{±1.0} 38.0 ±3.0 0.80 ^{±0.05} 1.47 ERG(X)3F

38.0 ^{±3.0}

0.80 ^{±0.05}

3.54

8.0 ^{±1.0}

24.00 ^{±1.50}

Ratings

Part No.	Power rating (70 ℃) (W)	Limiting element voltage*1 (V)	Maximum overload voltage ^{*2} (V)	Maximum intermittent overload voltage ^{*3} (V)	Dielectric withstanding voltage (V)	Resistance tolerance*4 (%)	ran	etance ge ^{*5} Ω) max.	T.C.R. (×10 ⁻⁶ /K)	Standard resistance value
ERG(X)12S	0.5	300	600	600	350	G (±2) J (±5)	0.2	22 k 47 k	±350	E 24
ERG(X)1S ERG(X)1F	1	350	600	600	350	G (±2) J (±5)	1 0.2	68 k 100 k	±350	E 24
ERG(X)2S ERG(X)2F	2	350	700	1000	600	G (±2) J (±5)	1 0.22	100 k 100 k	±350	E 24
ERG(X)3S ERG(X)3F	3	350	700	1000	1000	G (±2) J (±5)	1 0.22	100 k 100 k	±300	E 24
ERG(X)5S ERG(X)5F	5	500	1000	1500	1000	G (±2) J (±5)	1 0.33	100 k 100 k	±200	E 24

ERG(X)5S


ERG(X)5F

* Z type is non standard resistance values.

Code	Part No.	Res.tol.	Resistance value $range(\Omega)$	Code	Part No.	Res.tol.	Resistance value range(Ω)
	125	±2 %	0.1 to 0.91		2S	±2 %	0.1 to 0.91
Z	123	±5 %	0.1 to 0.18	7	2F	±5 %	0.1 to 0.2
۷	1S	±2 %	0.1 to 0.91		3S	±2 %	0.1 to 0.91
	1F	±5 %	0.1 to 0.18		3F	±5 %	0.1 to 0.2

Power derating curve

For resistors operated in ambient temperatures above 70 $^{\circ}$ C, power rating shall be derated in accordance with the figure on the right.



^{*1:} Rated Continuous Working Voltage (RCWV) shall be determined from RCWV=√Power Rating × Resistance Value, or Limiting Element Voltage listed above, whichever less.

^{*2:} Overload (Short-time Overload) Test Voltage (SOTV) shall be determined from SOTV=2.5×Power Rating or max. Overload Voltage listed above whichever less.

^{*3:} Intermittent Overload Test Voltage (IOTV) shall be determined from IOTV=4.0×Power Rating or max. Intermittent Overload Voltage listed above whichever less.

^{*4:} Resistance tolerance is of use besides range listed, please inquire.


^{*5:} Resistance Range type ERG : \geq 10 Ω , type ERX : \leq 9.1 Ω

^{*6:} As for the low resistance value range, "Z" is given to the part number. (Refer to the explanation of part numbers.)





Taped & Box

Stand-off taped & Box



ERG(X) = S = U = = V






Unit : mm

									Uni	t : mm
Part No.	Standard Taping dimensions Part No. quantity							Box		
	(pcs/box)	р	50×P	W	Н	W_1	ød	а	b	С
ERG(X)12S□□□□□V	2,000	5.0 ^{±0.3}	250 ^{±2}	52.0 ^{±1.5}	-	-	0.65 ^{±0.05}	85	80	255
ERG(X) 1SDDDDDV	2,000	5.0 ^{±0.3}	250 ^{±2}	52.0 ^{±1.5}	-	-	0.65 ^{±0.05}	85	80	255
ERG(X) 1SOUDOOV	2,000	5.0	250	52.0	12.0 0	1.20 +0.15	0.05	65	80	233
ERG(X) 2SDDDDDV	1 000	5.0 ^{±0.3}	250 ^{±2}	52.0 ^{±1.5}	-	-	0.80 ±0.05	85	80	255
ERG(X) 2SDUDDDV	1,000	5.0	250	52.0	15.5 0	1.40 +0.15	0.60	65	80	255
ERG(X) 3SDDDDDV	1 000	10.0 ±0.5	500 ^{±2}	74.0 ^{±2.0}	-	-	0.80 ±0.05	105	100	325
ERG(X) 3S□U□□□V	1,000	10.0	300	74.0	23.0 0	1.40 +0.15	0.00	105	100	323


Cut & Formed type





Part No.	Standard quantity	Dimensions							
	(pcs/box)	L	øD	S	h	h ₂			
ERG(X)12SDDDDP	1,000	6.35 ^{+0.65} _{-0.35}	2.3 +0.5 - 0.3	10.0 ^{±1.5}	4.0 ^{±1.5}	4.0 ^{±1.5}			
ERG(X)1SDDDDDP	1,000	9.00 +1.50 - 1.00	2.8 ^{±0.5}	12.5 ^{±1.5}	4.0 ^{±1.5}	4.0 ^{±1.5}			
ERG(X)2SDDDDDP	1,000	12.00 +1.50 - 1.00	4.0 ^{±1.0}	15.0 ^{±1.5}	6.0 ^{±1.5}	4.0 ^{±1.5}			
ERG(X)3SDDDDDP	1,000	15.00 ^{±1.50}	5.5 ^{±1.0}	20.0 ^{±2.0}	6.5 ^{±1.5}	4.0 ^{±1.5}			
ERG(X)5SDDDDDP	500	24.00 ^{±1.50}	8.0 ^{±1.0}	30.0 ^{±2.0}	7.5 ^{±1.5}	4.0 ^{±1.5}			


ERG(X) = F = = = = H



						Unit: mm			
Part No.	Standard guantity	Dimensions							
	(pcs/box)	L	øD	S	h	h ₂			
ERG(X)1F0000H	1,000	9.0 +1.5 - 1.0	2.8 ^{±0.5}	12.5 ^{±1.5}	8 ^{±2}	4.0 ^{±1.5}			
ERG(X)2F□□□□H	1,000	12.0 ^{+1.5} _{-1.0}	4.0 ^{±1.0}	15.0 ^{±1.5}	8 ^{±2}	5.0 ^{±1.5}			
ERG(X)3F000H	1,000	15.0 ±1.5	5.5 ^{±1.0}	20.0 ^{±2.0}	10 ^{±2}	5.0 ^{±1.5}			
ERG(X)5F000H	500	24.0 ±1.5	8.0 ^{±1.0}	30.0 ^{±2.0}	10 ^{±2}	5.0 ^{±1.5}			




For panasert automatic insertion machine radial taped & Box



Unit: mm


	Dimensions											
Р	12.7±1.0	W	18.0±0.5		12S	32 max.		12S	6.35 ^{+0.65} - 0.35		12S	2.3 +0.5 - 0.3
P ₀	12.7±0.3	W_1	9.0±0.5	H_1	1S	32 max.	Α	1S	9.0 ^{+1.5} - 1.0	øD	1S	2.8±0.5
P ₁	3.85±0.70				2S	38 max.		2S	12.0 ^{+1.5} - 1.0		2S	4.0±1.0
P ₂	6.35±1.00			H ₀		16.0±0.5	ød		0.65±0.05			
F	5.0±0.8			øD ₀		4.0±0.2						

• Radial Tape Package Specifications



Part No.	Standard quantity	Unit : mr Dimensions			
	(pcs/box)	а	b	С	
ERG(X)12S□□□□E	2,000	46	130	335	
ERG(X) 1SDDDDDE	2,000	46	130	335	
ERG(X) 2SDDDDDE	1,000	49	100	335	

For Panasert Au to mat ic Insertion Machine Radial Taped & Box




	Dimensions	(mm)		Dimensions	(mm)
Р	12S	12.7±1.0	øD0	12S, 1S, 2S, 3S	4.0±0.2
P	1S, 2S, 3S	30.0±1.0		12S	6.35 ^{+0.65} - 0.35
P_0	12S	12.7±0.3	Α	1S	9.0 ^{+1.5} -1.0
1 0	1S, 2S, 3S	15.0±0.3	, ,	2S	12.0 ^{+1.5} -1.0
P ₁	12S	6.35±1.00		3S	15.0±1.5
	1S, 2S, 3S	7.5±1.0		12S	11.2 max.
P ₂	12S	3.85±0.70	В	1S	14.0 max.
Г2	1S, 2S, 3S	3.75±0.50	В	2S	17.0 max.
F	12S	5.0±0.5		3S	21.0 max.
Г	1S, 2S, 3S	7.5±0.8		12S	2.3 +0.5
W	12S, 1S, 2S, 3S	18.0±0.5	øD	1S	2.8±0.5
W_1	12S, 1S, 2S, 3S	9.0±0.5	טש	2S	4.0±1.0
	12S	16.0±0.5		3S	5.5±1.0
H_0	1S, 2S	18.0±1.0	ød	12S	ø0.65±0.05
	3S	19.0±1.0	Øu	1S, 2S, 3S	ø0.80±0.05
-	12S	6.5 +0.6 0			
H_1	1S, 2S	6.5 ^{+1.0} ₀			
	3S	8.0 +1.0 0			




For Panasert Au to mat ic Insertion Machine Radial Taped & Box

 $ERG(X)\Box F\Box S\Box \Box \Box E$ (1F, 2F, 3F)



	Dimension	ns (mm)		Dimensio	ons (mm)		
Р	30.	0±1.0	H ₂	1.0±0.3			
P ₀	15.	0±0.3	φD_0	4	4.0±0.2		
P ₁	7.5	5±1.0		1F	9.0 +1.5		
P ₂	3.75	5±0.50	Α	2F	12.0 +1.5 - 1.0		
F	7.5	5±0.8		3F	15.0±1.5		
W	18.	18.0±0.5		1F	14.0 max.		
W_1	9.0	0±0.5	В	2F	17.0 max.		
H ₀	16	5.0 +1.0 0		3F	21.0 max.		
	1F	7.0 +1.0 0		1F	2.8±0.5		
H_1	2F	8.0 +1.0 0	φ D	2F	4.0±1.0		
	3F	9.0 +1.0 0		3F	5.5±1.0		
			φ d	0.80±0.05			

Radial Tape Package Specifications




Part No.	Standard Quantity	Dimensions (mm)				
	(pcs/box)	а	b	С		
ERG(X)12S□W□□□E	2,000	46	145	325		
ERG(X) 1SOWOODE	1,000	49	150	317		
ERG(X) 1FOSOOOE	1,000	49	130	317		
ERG(X) 2SOWOODE	500	49	150	317		
ERG(X) 2FDSDDDE	300	49	150	317		
ERG(X) 3FDSDDDE	500	49	190	315		



Hot-spot Temperature (for Reference)

The temperature of the resistor body increases with the curve below. A touching vinyl wire may cause damages to resistor element. Do not place vinyl wires around resistors and be sure to consider where the resistors will be placed.



Safety Precautions

The following are precautions for individual products. Please also refer to the common precautions for Fixed Resistors in this catalog.

1. Transient voltage


If there is a possibility that the transient phenomenon (significantly high voltage applied in a short time) may occur or that a high voltage pulse may be applied, make sure to evaluate and check the characteristics of Metal(Oxide) Film Resistors (hereafter called the resistors) mounted on your product rather than only depending on the calculated power limit or steady-state conditions to complete the design or decide to use the resistors.

- 2. The resistors are covered with a special coating. Do not apply shock or vibration to them, or pinch them with long-nose pliers. Otherwise, the resistors may be damaged.
- 3. Do not apply excessive tension to the lead-connected sections. When bending the lead wire, do not apply excessive stress to the resistors and provide the wire with a natural curvature.
- 4. Do not brush the resistors during or after the cleaning process, which may be conducted after soldering. Otherwise, the coating film may be damaged.



(Data for Reference)

Pulse Char ac ter is tics (Usual)



 $\begin{array}{lll} P_P & : & \text{Pulse limit power (W)} \\ V_P & : & \text{Pulse limit voltage (V)} \\ t & : & \text{Pulse continuous time (s)} \end{array}$

T : Period (s)

 V_R : Rated voltage (V) P : Rated power (W) R : Resistance value (Ω)

 $V_{p \text{ max.}}$: Max. pulse limit voltage (V)

Withstand pulse limit power is calculated by the next method.

$$\begin{array}{lll} P_P & = & K \cdot P \cdot T/_t \\ V_P & = & \sqrt{K \cdot P \cdot R \cdot T/_t} \end{array}$$

Reference to the right about a fixed number of $V_{p \text{ max.}}$

- T>1(s) \rightarrow T=1(s)
- \bullet T/t>100 \rightarrow T/t =100
- \bullet P_P<P \rightarrow P stands for P_P

 $(VP < VR \rightarrow VR \text{ stands for } VP)$

- Added voltage $\leq V_{pmax.}$
- P_P or V_P is referent value

Conditions: Pulse added time=1000 h

Resistance change = ± 5 %

Room temperature

Part No.	К	Vpmax. (V)
ERG(X)12S	0.5	600
ERG(X) 1S	0.5	600
ERG(X) 2S	0.5	700
ERG(X) 3S	0.5	700
ERG(X) 5S	0.5	1000





Safety Precautions

The following are precautions for individual products. Please also refer to the common precautions for Fixed Resistors in this catalog.

- 1. Transient voltage
 - If there is a possibility that the transient phenomenon (significantly high voltage applied in a short time) may occur or that a high voltage pulse may be applied, make sure to evaluate and check the characteristics of Metal(Oxide) Film Resistors (hereafter called the resistors) mounted on your product rather than only depending on the calculated power limit or steadystate conditions to complete the design or decide to use the resistors.
- 2. The resistors are covered with a special coating. Do not apply shock or vibration to them, or pinch them with long-nose pliers. Otherwise, the resistors may be damaged.
- 3. Do not apply excessive tension to the lead-connected sections. When bending the lead wire, do not apply excessive stress to the resistors and provide the wire with a natural curvature.
- 4. Do not brush the resistors during or after the cleaning process, which may be conducted after soldering. Otherwise, the coating film may be damaged.

Guidelines and precautions regarding the technical information and use of our products described in this online catalog.

- If you want to use our products described in this online catalog for applications requiring special qualities or reliability, or for applications where the failure or malfunction of the products may directly jeopardize human life or potentially cause personal injury (e.g. aircraft and aerospace equipment, traffic and transportation equipment, combustion equipment, medical equipment, accident prevention, anti-crime equipment, and/or safety equipment), it is necessary to verify whether the specifications of our products fit to such applications. Please ensure that you will ask and check with our inquiry desk as to whether the specifications of our products fit to such applications use before you use our products.
- The quality and performance of our products as described in this online catalog only apply to our products when used in isolation. Therefore, please ensure you evaluate and verify our products under the specific circumstances in which our products are assembled in your own products and in which our products will actually be used.
- If you use our products in equipment that requires a high degree of reliability, regardless of the application, it is recommended that you set up protection circuits and redundancy circuits in order to ensure safety of your equipment.
- The products and product specifications described in this online catalog are subject to change for improvement without prior notice. Therefore, please be sure to request and confirm the latest product specifications which explain the specifications of our products in detail, before you finalize the design of your applications, purchase, or use our products.
- The technical information in this online catalog provides examples of our products' typical operations and application circuits. We do not guarantee the non-infringement of third party's intellectual property rights and we do not grant any license, right, or interest in our intellectual property.
- If any of our products, product specifications and/or technical information in this online catalog is to be exported or provided to non-residents, the laws and regulations of the exporting country, especially with regard to security and export control, shall be observed.

< Regarding the Certificate of Compliance with the EU RoHS Directive/REACH Regulations>

- The switchover date for compliance with the RoHS Directive/REACH Regulations varies depending on the part number or series of our products.
- When you use the inventory of our products for which it is unclear whether those products are compliant with the RoHS Directive/REACH Regulation, please select "Sales Inquiry" in the website inquiry form and contact us.

We do not take any responsibility for the use of our products outside the scope of the specifications, descriptions, guidelines and precautions described in this online catalog.





Safety Precautions (Common precautions for Fixed Resistors)

- When using our products, no matter what sort of equipment they might be used for, be sure to make a written agreement on the specifications with us in advance. The design and specifications in this catalog are subject to change without prior notice.
- Do not use the products beyond the specifications described in this catalog.
- This catalog explains the quality and performance of the products as individual components. Before use, check and evaluate their operations when installed in your products under the actual conditions for use.
- Install the following systems for a failsafe design to ensure safety if these products are to be used in equipment where a defect in these products may cause the loss of human life or other significant damage, such as damage to vehicles (automobile, train, vessel), traffic lights, medical equipment, aerospace equipment, electric heating appliances, combustion/gas equipment, rotating equipment, and disaster/crime prevention
- * Systems equipped with a protection circuit and a protection device.
- * Systems equipped with a redundant circuit or other system to prevent an unsafe status in the event of a single
- * Systems equipped with an arresting the spread of fire or preventing glitch.

(1) Precautions for use

- These products are designed and manufactured for general and standard use in general elec tron ic equipment. (e.g. AV equipment, home electric appliances, office equipment, information and communication equipment) For applications in which special quality and reliability are required, or if the failure or malfunction of the products may directly jeopardize life or cause threat of personal injury (such as for aircraft and aerospace equipment, traffic and transport equipment, combustion equipment, medical equipment, accident prevention and anti-theft devices, and safety equipment), please be sure to consult with our sales representative in advance and to exchange product specifications which conform to such applications.
- These products are not intended for use in the following special conditions. Before using the products, carefully check the effects on their quality and performance, and determine whether or not they can be used.
 - 1. In liquid, such as water, oil, chemicals, or organic solvent.
 - 2. In direct sunlight, outdoors, or in dust.
 - 3. In salty air or air with a high concentration of corrosive gas, such as Cl_2 , H_2S , NH_3 , SO_2 , or NO_X .
 - 4. Electric Static Discharge (ESD) Environment.
 - These components are sensitive to static electricity and can be damaged under static shock (ESD). Please take measures to avoid any of these environments.
 - Smaller components are more sensitive to ESD environment.
 - 5. Electromagnetic and Radioactive Environment.
 - Avoid any environment where strong electromagnetic waves and radiation exist.
 - 6. In an environment where these products cause dew condensation.
 - 7. Sealing or coating of these products or a printed circuit board on which these products are mounted, with resin or other materials.
- These products generate Joule heat when energized. Carefully position these products so that their heat will not affect the other components.
- · Carefully position these products so that their temperatures will not exceed the category temperature range due to the effects of neighboring heat-generating components. Do not mount or place heat-generating components or inflammables, such as vinyl-coated wires, near these products.
- Note that non-cleaning solder, halogen-based highly active flux, or water-soluble flux may deteriorate the performance or reliability of the products.
- Carefully select a flux cleaning agent for use after soldering. An unsuitable agent may deteriorate the performance or reliability. In particular, when using water or a water-soluble cleaning agent, be careful not to leave water residues. Otherwise, the insulation performance may be deteriorated.
- Do not apply flux to these products after soldering. The activity of flux may be a cause of failures in these products.
- Refer to the recommended soldering conditions and set the soldering condition. High peak temperature or long heating time may impair the performance or the reliability of these products.
- · Recommended soldering condition is for the guideline for ensuring the basic characteristics of the products, not for the stable soldering conditions. Conditions for proper soldering should be set up according to individual conditions.



- Do not reuse any products after removal from mounting boards.
- Do not drop these products. If these products are dropped, do not use them. Such products may have received mechanical or electrical damage.
- If any doubt or concern to the safety on these products arise, make sure to inform us immediately and conduct technical examinations at your side.

(2) Precautions for storage

The performance of these products, including the solderability, is guaranteed for a year from the date of arrival at your company, provided that they remain packed as they were when delivered and stored at a temperature of 5 °C to 35 °C and a relative humidity of 45 % to 85 %.

Even within the above guarantee periods, do not store these products in the following conditions. Otherwise, their electrical performance and/or solderability may be deteriorated, and the packaging materials (e.g. taping materials) may be deformed or deteriorated, resulting in mounting failures.

- 1. In salty air or in air with a high concentration of corrosive gas, such as Cl₂, H₂S, NH₃, SO₂, or NO_x.
- 2. In direct sunlight.

(3) AEC-Q200 Compliant

The products are tested based on all or part of the test conditions and methods defined in AEC-Q200. Please consult with Panasonic for the details of the product specification and specific evaluation test results, etc., and please review and approve Panasonic's product specification before ordering.

<Package markings>

Package markings include the product number, quantity, and country of origin.

In principle, the country of origin should be indicated in English.





Safety Precautions (Common precautions for Surface Mount Resistors)

The following are precautions for individual products. Please also refer to the common precautions for Fixed Resistors in this catalog.

- Take measures against mechanical stress during and after mounting of Surface Mount Resistors (hereafter called the resistors) so as not to damage their electrodes and protective coatings. Be careful not to misplace the resistors on the land patterns. Otherwise, solder bridging may occur.
- Keep the rated power and ambient temperature within the specified derating curve. Some circuit boards, wiring patterns, temperatures of heat generated by adjacent components, or ambient temper a tures can become factors in the rise of the temperature of the resistors, regardless of the level of power applied. Therefore, check the conditions before use and op timize them so as not to damage the boards and peripheral components.
 - Make sure to contact us before using the resistors under special conditions.
- If a transient load (heavy load in a short time) like a pulse is expected to be applied, check and evaluate the operations of the resistors when installed in your products before use. Never exceed the rated power. Otherwise, the performance and/or reliability of the resistors may be impaired.
- Transient voltage If there is a possibility that the transient phenomenon (significantly high voltage applied in a short time) may occur or that a high voltage pulse may be applied, make sure to evaluate and check the characteristics of resistors mounted on your product rather than only depending on the calculated power limit or steady-state conditions.
- If the resistors are to be used in high frequency circuits, carefully check the operation before use. 5. Such circuits change the electrical characteristics of the resistors.
- Before using halogen-based or other high-activity flux, check the possible effects of the flux residues on the 6. performance and reliability of the resistors.
- 7. When soldering with a soldering iron, never touch the resistors'bodies with the tip of the soldering iron. When using a soldering iron with a high temperature tip, finish soldering as quickly as possible (within three seconds at 350 °C max.).
- Mounting of the resistors with excessive or insufficient wetting amount of solder may affect the connection reliability or the performance of the resistors. Carefully check the effects and apply a proper amount of solder for use.
- 9. When the resistors' protective coatings are chipped, flawed, or removed, the characteristics of the resistors may be impaired. Take special care not to apply mechanical shock during automatic mounting or cause damage during handling of the boards with the resistors mounted.
- 10. Do not apply shock to the resistors or pinch them with a hard tool (e.g. pliers and tweezers). Otherwise, the resistors' protective coatings and bodies may be chipped, affecting their performance.
- 11. Avoid excessive bending of printed circuit boards in order to protect the resistors from abnormal stress.
- 12. Do not immerse the resistors in solvent for a long time. Before using solvent, carefully check the effects of immersion.
- 13. Do not apply excessive tension to the terminals.